

TAB WASHER RELOCATING: WIPER TIMER ROTARY SWITCH

Should the Tab Washer accidentally become dislodged during installation simply replace it, tab side down, ensuring that the tab is located in the hole marked with the number 6.

